## MONUMENT RECORD State of Indiana - County of Monroe

Section: 17


Township: 8 North

Range: 1 East

Corner ID: Sa Cr G-09

Monument Description & Remarks: Found galvanized, crimped Iron Pipe, 1 1/8" across top at North 1/4 corner of section. Iron Pipe was well flagged - new and old pink flagging. Probed for buried stones but found no trace of old monuments.

References on file in the County Surveyor's Office: Survey by Bledsoe Tapp & Co., Inc., recorded in Book 2,



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document, was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the months of the given under my hand and seal this 12th day of January, 1998.

SEAL

SEAL

Administered by: Surveyor Review Boar

SEAL